
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —							
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-199	Smoke	7/27/2009	ADS/TM	S15C018MH	Dry	Yes	614.66



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —							
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-199	Smoke	7/27/2009	ADS/TM	S15C018MH	Dry	Yes	614.66

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S15A008G1	S15A008MH	S15A037MH	181.244	8
S15A037G1	S15A037MH	S15C018MH	318.332	8
S15C018G1	S15C018MH	S15C041MH	50.4251	8
S15C041G1	S15C041MH	S15C043MH	64.6627	8

Observations & Photos

Obs_ID S1028-199-OB01 **Address** 604 Whitmore Ave

StatusPrivateSourceCleanoutLocationYard - front

Nearest MH S15C_018MH

Comments Smoke from cleanout in front yard. 604

Whitmore Ave.



Picture \S1028-199-OB01-P01.jpg

Comments Front of house, 604 Whitmore Ave.

Obs_ID S1028-199-OB02 **Address** 608 Whitmore Ave

Status Private **Source** Cleanout

Location Yard - front **Nearest MH** S15C__018MH

Comments Smoke from above-grade cleanout in front

yard. 608 Whitmore Ave.



Picture \S1028-199-OB02-P01.jpg

Comments Front of house, 608 Whitmore

Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary Date Ground Total Notification Company / **Test ID Test Type Inspected Blower MH** Condition Length Made? Super. S1028-199 Dry Smoke 7/27/2009 ADS/TM S15C__018MH Yes 614.66

Obs_ID S1028-199-OB03 **Obs ID** S1028-199-OB04 **Address** 704 Whitmore Ave Address 726 Whitmore Ave **Status** Private Status Private Source Cleanout Source Cleanout Yard - front Location Location Yard - front Nearest MH S15A__037MH Nearest MH S15A__008MH

Comments Smoke from cleanout in front yard. 704 **Comments** Smoke from cleanout in front yard. 726

Whitmore Ave. Whitmore Ave.



Picture \S1028-199-OB03-P01.jpg

Comments Front of house, 704 Whitmore **Comments** Front of house, 726 Whitmore



Picture \S1028-199-OB04-P01.jpg

